

## **Utility Conflict Report**

IER	Utility	Jtility SAWS		Corridor	NOGALITOS		SITE PHOTOS	
OWNER	Contact	ontact NINA BITTL		.E <b>ID</b>				
	Utility		WATER				HULLE II THE	
INFO	Size and Material		STANDARD WATER METER, STEEL				77am	
GENERAL	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			UTE		
GEN	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station 1	43+52.32					W REPAIR (SECOND CONTROL OF CONTR	
	Offset 2	26.0926						
	Latitude +	+29.395582						
	Longitude -	-98.51586						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/13/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Top of meter to surface = 4" Rubber oval lid thickness = 2" Sidewalk width = 4'-0" Meter to back of sidewalk = approx. 4'-6"		5"			
	<b>Date Collected</b> 7/11/2018 10:01:19 AM <b>Date Modified</b> 8/14/2018 4:38:26 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800