

## Utility Conflict Report

|                     |                                     |  |                       |                      |                    |
|---------------------|-------------------------------------|--|-----------------------|----------------------|--------------------|
| <b>OWNER</b>        | <b>Utility</b>                      | CPS  | <b>Corridor</b>       | NOGALITOS            | <b>SITE PHOTOS</b> |
|                     | <b>Contact</b>                      | JAKE MARTINEZ  | <b>ID</b>             | 3063                 |                    |
| <b>GENERAL INFO</b> | <b>Utility</b>                      | ELECTRIC   |                       |                      |                    |
|                     | <b>Size and Material</b>            | STANDARD POWER POLE, TIMBER  |                       |                      |                    |
|                     | <b>Accessible Route</b>             | ASSET IS INSIDE ACCESSIBLE ROUTE   |                       |                      |                    |
|                     | <b>Longitudinal or Crossing</b>     | CROSSING   |                       |                      |                    |
|                     | <b>Placement Relative to ROW</b>    | INSIDE ROW   |                       |                      |                    |
| <b>LOCATION</b>     | <b>Sheet No.</b>                    | 85   |                       |                      |                    |
|                     | <b>Station</b>                      | 134+46.20  |                       |                      |                    |
|                     | <b>Offset</b>                       | 21.77  |                       |                      |                    |
|                     | <b>Latitude</b>                     | +29.393564   |                       |                      |                    |
|                     | <b>Longitude</b>                    | -98.51756  |                       |                      |                    |
| <b>SUE</b>          | <b>Level of Investigation Req'd</b> | NONE   |                       |                      |                    |
|                     | <b>Test Hole No</b>                 | N/A  |                       |                      |                    |
|                     | <b>Test Hole Depth</b>              | N/A  |                       |                      |                    |
| <b>RESOLUTION</b>   | <b>Recommended Action</b>           | MINIMIZE - PROTECT IN PLACE  |                       |                      |                    |
|                     | <b>Estimated Resolution Date</b>    |  |                       |                      |                    |
|                     | <b>Resolution Status</b>            | UTILITY OWNER INFORMED OF UTILITY  |                       |                      |                    |
|                     | <b>Comment</b>                      | Pole to back of sidewalk = 1'-11"<br>Pole to back of curb = 1'-9"<br>Sidewalk width = 4'-9"<br>Pole diameter = 13"<br>No pole ID |                       |                      |                    |
|                     | <b>Date Collected</b>               |  | 7/11/2018 11:21:26 AM | <b>Date Modified</b> |                    |

