

Utility Conflict Report

| | | | | | | | |
|-----------------------|-------------------------------------|---|-----------------|----------------------|--------------------|-----------------------|--|
| OWNER | Utility | CPS | Corridor | SW MILITARY | SITE PHOTOS | | |
| | Contact | JAKE MARTINEZ | ID | 3148 | | | |
| GENERAL INFO | Utility | ELECTRIC | | | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | | | |
| | Accessible Route | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | CROSSING | | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | | |
| LOCATION | Sheet No. | 142 | | | | | |
| | Station | 583+77.04 | | | | | |
| | Offset | 15.9511 | | | | | |
| | Latitude | +29.356731 | | | | | |
| | Longitude | -98.54356 | | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | | |
| | Test Hole No | N/A | | | | | |
| | Test Hole Depth | N/A | | | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | | | |
| | Estimated Resolution Date | | | | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | Pole ID: 491663 Pole to front of sidewalk = 2'-8" Sidewalk width = 4'-3" Pole diameter = 14 1/2" | | | | | |
| Date Collected | | 7/31/2018 10:40:39 AM | | Date Modified | | 11/28/2018 6:59:12 AM | |

