

## **Utility Conflict Report**

IER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS
OWNER	Contact	ANN PECH	E	ID	3201		
NERAL IN	Utility		WATER				
	Size and Material		STANDARD WATER VALVE, CAST IRON				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						NIII
	Station						
	Offset						
	<b>Latitude</b> +29.508614						
	Longitude -	98.62953					
SUE	Level of Investiga	tion Req'd	NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended A	ction	NO CONFLIC	Т			
	Estimated Resolution Date		8/28/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Top of valve to Lid thickness : Front of wall to Water valve to	= 1 1/2" o valve = 10	)'-1"		
	Date Collected	8/17/2018 8:	12:47 AM	Date I	Modified	11/28/2	2018 6:59:12 AM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800