

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	BANDERA	SITE PHOTOS
	Contact	ANN PECHE	ID	3202	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD WATER METER, STEEL			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	260			
	Station	1439+50			
	Offset	-45			
	Latitude	+29.508481			
	Longitude	-98.62943			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date				
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Steel lid Unable to open lid Edge of driveway to utility = 1'-4 1/2" Edge of concrete channel to utility = 10"			
Date Collected		8/17/2018 8:17:37 AM		Date Modified 12/18/2018 4:54:11 PM	

