

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	BANDERA	SITE PHOTOS
	Contact	ANN PECHE	ID	3231	
GENERAL INFO	Utility	SANITARY SEWER			
	Size and Material	STANDARD MANHOLE, CAST IRON			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station				
	Offset				
	Latitude	+29.494260			
	Longitude	-98.61784			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/28/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Fence to manhole = 11" Unable to open manhole			
Date Collected		8/20/2018 9:09:44 AM	Date Modified		11/28/2018 6:59:12 AM

