

Utility Conflict Report

OWNER	Utility	TxDOT	Corridor	NOGALITOS	SITE PHOTOS		
	Contact	SUMAN SHRESTHA	ID	4076			
GENERAL INFO	Utility	UNKNOWN					
	Size and Material	UNKNOWN					
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.						
	Station	127+08.36					
	Offset	26.2972					
	Latitude	+29.392071					
	Longitude	-98.51893					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date	8/13/2018					
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Emergency vehicle crossing traffic signal Sidewalk width = 3'-10" Face of wall to base of pole = 1'-0" Sign vertical clearance = 7'-1"					
Date Collected		7/10/2018 2:13:49 PM		Date Modified		8/14/2018 4:38:26 PM	

