

Utility Conflict Report

| | | | | | | | |
|-----------------------|-------------------------------------|---|-----------------|----------------------|--------------------|-----------------------|--|
| OWNER | Utility | CPS | Corridor | SW MILITARY | SITE PHOTOS | | |
| | Contact | JAKE MARTINEZ | ID | 4146 | | | |
| GENERAL INFO | Utility | ELECTRIC | | | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | CROSSING | | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | | |
| LOCATION | Sheet No. | 155 | | | | | |
| | Station | 675+14.85 | | | | | |
| | Offset | 17.48 | | | | | |
| | Latitude | +29.356575 | | | | | |
| | Longitude | -98.51476 | | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | | |
| | Test Hole No | N/A | | | | | |
| | Test Hole Depth | N/A | | | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | | | |
| | Estimated Resolution Date | 11/21/2018 | | | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | Pole ID: 436609 Pole to back of curb = 3'-9" Sidewalk width = 6'-0" Pole to back of sidewalk = 1'-2" | | | | | |
| Date Collected | | 8/1/2018 11:23:36 AM | | Date Modified | | 11/28/2018 6:59:12 AM | |

