

Utility Conflict Report

OWNER	Utility	UNKNOWN	Corridor	SW MILITARY	SITE PHOTOS	
	Contact	UNKNOWN	ID	4164		
GENERAL INFO	Utility	UNKNOWN				
	Size and Material	UNKNOWN				
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing	CROSSING				
	Placement Relative to ROW	INSIDE ROW				
LOCATION	Sheet No.	158				
	Station	685+18.24				
	Offset	25.2469				
	Latitude	+29.356527				
	Longitude	-98.51170				
SUE	Level of Investigation Req'd	NONE				
	Test Hole No	N/A				
	Test Hole Depth	N/A				
RESOLUTION	Recommended Action	NO CONFLICT				
	Estimated Resolution Date					
	Resolution Status	NO RESOLUTION WAS REQUIRED				
	Comment	Vertically raised black pipe Back of sidewalk to pipe = 3'-2" Sidewalk width = 4'-1"				
Date Collected		8/2/2018 10:19:41 AM		Date Modified 11/28/2018 6:59:12 AM		

