

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS		
	Contact	ANN PECHE	ID	4166			
GENERAL INFO	Utility	WATER					
	Size and Material	STANDARD WATER VALVE, CAST IRON					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.	158					
	Station	686+13.74					
	Offset	22.19					
	Latitude	+29.356547					
	Longitude	-98.51141					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	NO CONFLICT					
	Estimated Resolution Date						
	Resolution Status	NO RESOLUTION WAS REQUIRED					
	Comment	Front of sidewalk to valve = 3'-6" Sidewalk width = 3'-11" Lid flange thickness = 3/8" Total lid thickness = 1 7/8" Valve box filled with dirt Top of valve to surface = unknown					
Date Collected		8/2/2018 10:31:26 AM		Date Modified		12/18/2018 4:27:07 PM	

