

## **Utility Conflict Report**

ER	Utility SAWS			Corridor	SW MILITA	Y	SITE PHOTOS	
OWNER	Contact	ANN PECHE		ID	4211			
<b>GENERAL INFO</b>	Utility		WATER					
	Size and Material		STANDARD WATER METER, CAST IRON			ON		
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUT			UTE		
	Longitudinal or Crossing		CROSSING					
Ö	Placement Relative to ROW		INSIDE ROW				The second second	
LOCATION	Sheet No. 1	66						
	Station 7	20+01.30						
	Offset 2	1.1522						
	Latitude +29.356577							
	Longitude -	-98.50078						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	<b>Resolution Status</b>		NO RESOLUTION WAS REQUIRED					
	Comment		Back of wall to meter = 1'-9"					
			Top of meter to surface = 3" Sidewalk width = 6'-8"					
			Box adjacent to meter is filled with dirt					
	Date Collected 8/7/2018 8:16:04 AM Date Modified 11/28/						2018 6:59:12 AM	

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com