

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	4594	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD WATER METER, CAST IRON			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station	661+28.72			
	Offset	22.675			
	Latitude	+29.356524			
	Longitude	-98.519200			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment				
Date Collected		12/17/2018 1:40:19 PM		Date Modified 12/17/2018 1:49:51 PM	

