

Utility Conflict Report

OWNER	Utility	SAWS	Corridor	SW MILITARY	SITE PHOTOS
	Contact	ANN PECHE	ID	7102	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD WATER METER, STEEL			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	194			
	Station	853+82.32			
	Offset	-26.8325			
	Latitude	+29.356786			
	Longitude	-98.53091			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date				
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Meter adjacent to back of sidewalk Top of meter to surface = 2" Meter filled with dirt			
Date Collected		8/3/2018 3:59:51 PM		Date Modified 11/28/2018 6:59:12 AM	

