

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	SW MILITARY	SITE PHOTOS	
OWNER	Contact	ANN PECHE		ID	7135		
<b>GENERAL INFO</b>	Utility		WATER				
	Size and Material		STANDARD WATER METER, STEEL				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 179					-	
	Station 7	69+09.48				The Party	
	Offset -:	23.843					
	Latitude +29.358237					- A	
	Longitude -98.55753						
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Meter filled with dirt and water Top of dirt to surface = 5.5"				
			Back of driveway apron to meter = 2'-7.5"				
	Date Collected 8/6/2018 11:25:02 AM Date Modified 11/28/2018 6:59:12 AM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com