

Utility Conflict Report

| ER | Utility | SAWS | | Corridor | SW MILITAF | RY | SITE PHOTOS | |
|---------------------|--|-----------|--|----------|------------|----|-------------|--|
| OWNER | Contact | ANN PECH | E | ID | 7145 | | | |
| GENERAL INFO | Utility | | SANITARY SEWER | | | | | |
| | Size and Material | | STANDARD MANHOLE, CAST IRON | | | | | |
| | Accessible Route | | ASSET IS OUTSIDE ACCESSIBLE ROU | | UTE | | | |
| | Longitudinal or Crossing | | CROSSING | | | | A CARLES | |
| | Placement Relative to ROW | | INSIDE ROW | | | | | |
| LOCATION | Sheet No. 1 | 74 | | | | | | |
| | Station 7 | 56+14.06 | | | | | | |
| | Offset - | 18.2851 | | | | | | |
| | Latitude +29.358606 | | | | | | | |
| | Longitude - | -98.56170 | | | | | | |
| SUE | Level of Investigation Req'd | | NONE | | | | | |
| | Test Hole No | | N/A | | | | | |
| | Test Hole Depth | | N/A | | | | | |
| RESOLUTION | Recommended Action | | NO CONFLICT | | | | | |
| | Estimated Resolution Date | | | | | | | |
| | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | | Manhole adjacent to back of sidewalk Sidewalk width = 4'-0" Top of cone to surface = 1'-0 1/2" | | | | | |
| | Date Collected 8/6/2018 1:34:54 PM Date Modified 11/28/2018 6:59:12 AM | | | | | | | |

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800

San Antonio I Austin I Houston I Fort Worth I Dallas

Transportation | Water Resources | Land Development | Surveying | Environmental

2000 NW Loop 410, San Antonio, TX 78213 T: 210.375.9000 www.Pape-Dawson.com