



Utility Conflict Report

OWNER	Utility	SAWS	Corridor	BANDERA	SITE PHOTOS
	Contact	ANN PECHE	ID	8018	
GENERAL INFO	Utility	WATER			
	Size and Material	STANDARD WATER METER, CAST IRON			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station	N/A			
	Offset	N/A			
	Latitude				
	Longitude				
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date				
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY			
	Comment	Bandera corridor has not yet been surveyed This record is a placeholder and is not a confirmed utility conflict			
Date Collected		Date Modified		8/17/2018 3:17:37 PM	

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800