

Utility Conflict Report

| | | | | | |
|-----------------------|-------------------------------------|--|-----------------|--|--------------------|
| OWNER | Utility | CPS | Corridor | SW MILITARY | SITE PHOTOS |
| | Contact | JAKE MARTINEZ | ID | 7070 | |
| GENERAL INFO | Utility | ELECTRIC | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | |
| | Longitudinal or Crossing | CROSSING | | | |
| | Placement Relative to ROW | INSIDE ROW | | | |
| LOCATION | Sheet No. | 152 | | | |
| | Station | 901+91.16 | | | |
| | Offset | -17.09 | | | |
| | Latitude | +29.356760 | | | |
| | Longitude | -98.51588 | | | |
| SUE | Level of Investigation Req'd | NONE | | | |
| | Test Hole No | N/A | | | |
| | Test Hole Depth | N/A | | | |
| RESOLUTION | Recommended Action | ACCOMODATE - RELOCATION | | | |
| | Estimated Resolution Date | | | | |
| | Resolution Status | UTILITY OWNER INFORMED OF UTILITY | | | |
| | Comment | Pole marking: 8 Pole diameter = 10" Pole to back of sidewalk = 3'-11" Back of curb to pole = 3'-1" CATV cable Dead end pole to be removed, attachments to be relocated with ID 7069 | | | |
| Date Collected | | 8/3/2018 11:41:58 AM | | Date Modified 11/21/2018 2:51:37 PM | |

