



Utility Conflict Report

OWNER	Utility	SAWS	Corridor	BANDERA	SITE PHOTOS
	Contact	NINA BITTLE	ID	4586	
GENERAL INFO	Utility	SANITARY SEWER			
	Size and Material	UNKNOWN			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	LONGITUDINAL			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	333			
	Station	2027+05			
	Offset	-25			
	Latitude	+29.484896			
	Longitude	-98.59485			
SUE	Level of Investigation Req'd	QLA			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	ACCOMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY CONFLICT CREATED			
	Comment	GIS indicates that a water and/or sanitary sewer line could be located beneath proposed bus pad. Request As-builts for line depth verification			
Date Collected		Date Modified		11/21/2018 2:51:37 PM	