

Utility Conflict Report

| | | | | | | | |
|-----------------------|-------------------------------------|--|-----------------|----------------------|--------------------|----------------------|--|
| OWNER | Utility | CPS | Corridor | NOGALITOS | SITE PHOTOS | | |
| | Contact | JAKE MARTINEZ | ID | 3053 | | | |
| GENERAL INFO | Utility | ELECTRIC | | | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | | | |
| | Accessible Route | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | CROSSING | | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | | |
| LOCATION | Sheet No. | | | | | | |
| | Station | 139+53.57 | | | | | |
| | Offset | -28.401 | | | | | |
| | Latitude | +29.394873 | | | | | |
| | Longitude | -98.51673 | | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | | |
| | Test Hole No | N/A | | | | | |
| | Test Hole Depth | N/A | | | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | | | |
| | Estimated Resolution Date | 8/13/2018 | | | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | Pole ID: LW 46784; PL 47922 Pole marking: 1903 Sidewalk width = 4'-1" Pole to back of sidewalk = 9" | | | | | |
| Date Collected | | 7/11/2018 9:03:10 AM | | Date Modified | | 8/14/2018 4:38:26 PM | |

