

Utility Conflict Report

OWNER	Utility	TxDOT	Corridor	NOGALITOS	SITE PHOTOS
	Contact	SUMAN SHRESTHA	ID	4076	
GENERAL INFO	Utility	UNKNOWN			
	Size and Material	UNKNOWN			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.				
	Station	127+08.36			
	Offset	26.2972			
	Latitude	+29.392071			
	Longitude	-98.51893			
SUE	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/13/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Emergency vehicle crossing traffic signal Sidewalk width = 3'-10" Face of wall to base of pole = 1'-0" Sign vertical clearance = 7'-1"			
	Date Collected		7/10/2018 2:13:49 PM	Date Modified	

