

Utility Conflict Report

| ER | Utility | CPS | | Corridor | SW LOOP | 410 | SITE PHOTOS | | |
|---|------------------------------|-----------|---|----------|---------|-----|-------------|--|--|
| OWNER | Contact | JAKE MAR | INEZ | ID | 7005 | | | | |
| GENERAL INFO | Utility | | GAS | | | | | | |
| | Size and Material | | STANDARD GAS VALVE, CAST IRON | | | | | | |
| | Accessible Route | | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | | | | |
| | Longitudinal or Crossing | | CROSSING | | | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | | | | |
| LOCATION | Sheet No. | | | | | | | | |
| | Station 2 | 283+58.68 | | | | | | | |
| | Offset -18.5162 | | | | | | | | |
| | Latitude +29.374182 | | | | | | | | |
| | Longitude -98.63867 | | | | | | | | |
| SUE | Level of Investigation Req'd | | NONE | | | | | | |
| | Test Hole No | | N/A | | | | | | |
| | Test Hole Depth | | N/A | | | | | | |
| RESOLUTION | Recommended Action | | NO CONFLICT | | | | | | |
| | Estimated Resolution Date | | | | | | | | |
| | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | | | |
| | Comment | | Gas valve in concrete riprap Edge of pavement to valve = 7'-6" Top of valve to surface = 3.5" Lid thickness = 1 5/8" Raise valve cover flush with sidewalk improvements to avoid more complex telecommunications manhole adjustment | | | | | | |
| Date Collected 8/2/2018 8:58:08 AM Date Modified 8/14/2018 4:38:26 PM | | | | | | | | | |

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800