


Data Collection Report

| | | | | |
|-----------------------|--|---|----------------------|------------|
| GENERAL INFO | LOCID | 144 | Latitude | +30.731929 |
| | Project | CR 363 | Longitude | -97.289883 |
| | | | Element | Drainage |
| | Map Link | https://maps.google.com/maps?t=h&q=+30.731929,-97.289883 | | |
| | Field Notes | ~15" circular CMP 90% buried | | |
| SITE PHOTOS |  | | | |
| Photo 1 | | | | |
| Date Collected | | 6/20/2018 12:30:31 PM | Date Modified | |
| | | | 6/20/2018 4:18:48 PM | |

Data Collection Report

SITE PHOTOS



Photo 2



Photo 3

Date Collected 6/20/2018 12:30:31 PM

Date Modified 6/20/2018 4:18:48 PM